

DESIGN-BUILD SERVICES

Northeast Water Purification Plant Expansion






Construction Progress – EWP 1 Site Development August 22, 2018

- Dewatering and Final grading Ponds 1, 2, and 3
- Clearing and grubbing South East corner
- Hauling unsuitable soils off-site
- Embanking Road 2
- Laying CTB on Road 3
- Installing 20"RW pipeline
- Installing fence on south property line.







CTB on Rd 3

Embanking/Compacting Rd 2









Cleared area to tie into existing wetland outfall







Backfilling and Compacting 20" RW Pipeline









Another Gator Caught on site



Construction Progress – EWP 4 – Raw Water Corridor August 22, 2018

- Maintaining dewatering system
- Cutting pipeline excavation, and installing shoring system
- Installing fence in East corridor, South side
- Installing dewatering system in East corridor





Installing shaft entryway cage ladder





Welding Portal Ring







Cutting Pipeline Trench










Construction Progress – EWP 2 Filter Structure & TPS August 22, 2018

- Installing formwork for foundation slabs
- Tying rebar for foundation slab
- Excavating TPS pump cans and backfilling with crushed concrete
- Poured base manifold slab



Forming and reinforcing base manifold slabs








Pouring base manifold slabs







Pouring base manifold slabs





Finished the concrete








Excavating TPS









TPS Crushed Concrete Backfill







Construction Progress – EWP 6 August 22, 2018

- Mobilizing to perform test piles
- Assembling and setting crane

Assembling crane for Test piles







Mobilizing & Assembling crane and for Test piles





Positioning crane for test piles install





